



Solder Turret Output Connectors

For Linear Power Supplies

Examples of how to solder wire to Solder Turrets

The double turrets, right side, are used on Condor / SLPE linear power supplies (except F & G case)

